| | Туре | Hits | Search Text | DBs |
|---|------|------------|---|-------|
| 1 | BRS | 13934 1 | resistance and (coil or winding) | USPAT |
| 2 | BRS | 61703 6 | calculat\$4 or estimat\$4 | USPAT |
| 3 | BRS | 46103 | flux and voltage | USPAT |
| 4 | BRS | 85434 0 | current | USPAT |
| 5 | BRS | 4326 | (resistance and (coil or winding)) and (calculat\$4 or estimat\$4) and (flux and voltage) and current | USPAT |
| 6 | BRS | 18197 | (winding or coil) near5 resistance | USPAT |
| 7 | BRS | 1317 | ((resistance and (coil or winding)) and (calculat\$4 or estimat\$4) and (flux and voltage) and current) and ((winding or coil) near5 resistance) | USPAT |
| 8 | BRS | 69228 | resistance.ab. | USPAT |
| 9 | BRS | 105 | (((resistance and (coil or winding)) and (calculat\$4 or estimat\$4) and (flux and voltage) and current) and ((winding or coil) near5 resistance)) and resistance.ab. | USPAT |

| ٠ | Туре | L# | Hits | Search Text | DBs | Time Stamp | Comm ents |
|---|------|----|------------|---------------------------------|-----|----------------------|--------------|
| 1 | BRS | L1 | | (resistance or temperature).ti. | _ | 2003/06/ 16 15:27 | |
| 2 | BRS | L2 | 1336 | reluctance.ab. | | 2003/06/ 16 15:28 | |
| 3 | BRS | L3 | 5496 01 | motor | | 2003/06/ 16 15:28 | |
| 4 | BRS | L4 | 2 | 1 and 2 and 3 | | 2003/06/ 16 15:28 | |